


Agenda


- Introduction
- Design
- Manufacture
- Assembly
- Conclusion

Introduction







Design




My Schematic



Working on Breadboard



My Layout





The PCBs

Theirs



Mine





Manufacture and Assembly

Design for Manufacturability

- Minimum copper trace width = 7mil
- Minimum copper trace spacing = 8mil
- Minimum hole size = 15mil
- Minimum annular ring = 10mil

Assembly



Conclusion

